

Er. Rabindra Nath Mishra  
B.E. (Civil), M.E. (Cal), MIE, MISTE, FIV  
Chartered Engineer, Surveyor & Loss assessor  
Ex. H.O.D. Civil Engg Department (Civil), Structural Engineer RDA  
Orissa Govt. Approved Valuer, Comp. Person of Factory of Bolers  
M-127455/9, F-16395, LM-18718, RDA-042/2017

ADHARSHILA  
GC-36 & 39, R.C.M.S. Complex  
S.T.I. Chowk, Rourkela-769004  
DIST- Sundargarh,  
Phone No. (0661)-2501215,  
Mob:-9437041215



ISO 9001 Registration  
ISO-9000-2008  
(Certified Company)

## STRUCTURAL STABILITY CERTIFICATE

### CERTIFICATE FOR STRUCTURAL STABILITY

With respect to the building works of erection, re-erection or for making alteration in the Front Educational Institution building of DR. A.N.K DAV PUBLIC SCHOOL, Over Khata No -2,3,4, PLOTNO-63/1,63/2,12,16,27,28,55, 60,61/1,62/1,64,65,66,67, 69,70,90,104/1,93,100,84,67, 58,59,80, 86,89,31,22/1,99,19/250,19,17,15,14,13,11,35,25,32,83,35,46,48, 49,50,56,68, 85,92,91,94,95/1,97,123/281,123/282,123/283,123/284,123/290,123/278,123/279,29,26, 23,34,36,37,38,39,40,41,42,43,44,45,47,51,52,53,54,36,37, 38,39,40,41,42,43,44, 45,47, 51,52,53,54. MOUZA-DURGAPUR (R.T.U NO-38), P.S :- Uditnagar, Tahasil-Rourkela, DIST- Sundargarh of Rourkela Municipality within the Development Plan Area of RDA, I certify structural plans and details of the building submitted for approval that the structural safety requirements for all situations including natural disasters like cyclone & earthquake etc. as applicable under Part-6 (Structural Design) of the National Building Code of India, 2005 and other relevant codes; and the information given therein is fully correct to the best of my knowledge. I undertake responsibility with regard to supervision of the work at each stage of construction, (laying of foundations & after casting of each floor) and submit the report to R.D.A. regularly to effect that the building is being constructed conforming to the approved plan and as per the structural plan prepared by me. I will be responsible and liable for any action by R.D.A./ Govt. if the plan/ design contain misrepresentation or fraudulent information and the construction is made in deviation to the approved plan or if there is any structural failure due to wrong/ unsafe structural design, use of low quality material and/ or poor workmanship endangering the in-mates, public & properties.

Signature of owner  
/Developer/Builders

Name:- LOKANATH PRADHAN.  
Address:- PRINCIPAL  
Principal

DAV PUBLIC SCHOOL, ROURKELA

Signature of the Registered Engineer/  
10/6/19

Rabindra Nath Mishra  
Structural Engineer With date and registration No.  
**ER. RABINDRA NATH MISHRA**  
Govt. Registered Structural Engineer  
Regd. No.-RTP/DTP (ST.ER)-043/2017

Self attested

[Signature]